


AC SPARK TESTER



AC Spark Tester 0-50KV@ 2KVA
Input-230vac (Single Phase) \pm 10%
Output-0-50KV.
Duty-Contiuouse
Control-manual.
Metering-AC Primary side.

Protection-

1. Fuse input side
2. A fast acting relay in case of fault/ when current exceed the preset value.
3. cage door.
4. control panel air cooled.
HV Transformers air cooled (at 15KV)
5. Trip & Trip by pass switch.

Indication:

LT on, HT on, Fault.

Push button:
HT ON

Meter type :
AC kV meter.
(size 96/96 Analog.

Impluse Counter : 99999

Accessories ;
Input lead 3meters.
Output lead 1.5meters.
Electrode box with brass ball chain

Size of set.
Panel (400mm/420mm/910mm) \pm 10%.